IN THE UNITED STATES PATENT & TRADEMARK OFFICE.

ATTORNEY DOCKET NUMBER: 200404411-1 IN RE APPLICATION OF: U.S. Patent No. 6,848,063 LISPTO CONFIRMATION CODE: 1127 APPLICATION NO.: 09/989.357 FILED: Nov. 20, 2001 EXAMINER: Robert Beansoliel GROUP ART UNIT: 2113 FOR: SYSTEM AND METHOD FOR SCRUBBING FRRORS IN VERY LARGE. MEMORIES 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS Sir The following is a request for a certificate of correction in Serial Number 09/989,357, now Patent Number 6,848,063. A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent. All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025. All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account. The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee

The exact locations where the errors appear in the patent and patent application are as follows:

is required, please charge the amount to the same Deposit Account.

In column 14, line 39, in Claim 17, after "method" insert - of --. (Amendment to claims filed on Aug. 19, 2004, page 8, in Claim 17, line 1)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

6/30/09

/Ted McCullough/

DATE

Name: Ted McCullough Registration No.: 56,231

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration P.O. Box 272400 Fort Collins, Colorado 80527-2400

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,848,063

APPLICATION NO.: 09/989,357

ISSUE DATE: Jan. 25, 2005

INVENTOR(S) : Thomas Lee Rodeheffer, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 14, line 39, in Claim 17, after "method" insert - - of --,

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration P. O. Box 272400 Fort Collins, Colorado 80527-2400

This collection of information to operate by 37 CFR (1922, seef 132), and 1424. The information is required to obtain on reason to mode for byte inspired to distribute on the CENTRO represents an appearance (Confidentiality in agreement page 38 US CT) and 37 CFR 18 LT Bins pollution is instanted to the 10 Own to complete, including updationing, response, and submitting the completed application form to the USFTO. Time will vary depending upon the individual term. Any comments on the associated formation of complete the firm that the upgestion for the endouge their firm than the distribution of CENTRO (VERTRO TERMO TO CONTROL TE